

PHONE : +94 -11- 2264203 FAX : +94 -11- 2259916 AFS : VCBIYOYX VCCCYAYX E-mail : aimhq@airport.lk ddgasr@caa.lk	DEMOCRATIC SOCIALIST REPUBLIC OF SRI LANKA AERONAUTICAL INFORMATION SERVICES (AIM/HQ) AIRPORT & AVIATION SERVICES (S. L.) (PRIVATE) LTD. BANDARANAIKE INTL AIRPORT COLOMBO KATUNAYAKE, SRI LANKA.	AIP SUPPLEMENT 05/24 04 APR 2024
--	--	---

AD

Limitations to ongoing aircraft operations at Bandaranaike International Airport Colombo (VCBI)

(AIP Supplement 01/24 is revised)

1. Introduction

- 1.1 The purpose of this AIP Supplement is to inform all aircraft operators about the limitations to ongoing aircraft operations due to construction work of new Terminal Building (T2) and associated new Pier Buildings at Bandaranaike International Airport Colombo.
- 1.2 The "Parking Stands Availability & Refueling Schedule", which was published by AIP Supplement 01/24-Appendix C is revised due to improvement of existing parking arrangements.

2. Limitations to ongoing aircraft operations

- 2.1. TWY E1 available only for aircraft taxi out operations.
- 2.2. Airside ground handling services are expected to delay due to the following airside rearrangements:
 - Revised shifted parking stand locations in Apron B and Apron C - (Refer Appendix A)
 - Shifted service roads around Apron B and Apron C - (Refer Appendix B).

3. Parking stands availability and refueling schedule



- 3.1 Availability of parking stands in Apron B and Apron C will be limited as mentioned in Appendix C.
- 3.2 Due to the shifting of parking stands, hydrant refueling system in Apron B and Apron C will be affected. The limitations therein are stated in Appendix C.
- 3.3 The refueling limitations for B15-B18 and C19-C26 where hydrant refueling will not be available shall prevail until the completion of the Terminal 2 project.



4. Cancellation



- 4.1 NOTAM A0221/24 is hereby superseded and refer NOTAM for further updates.
- 4.2 AIP Supplement 01/24 is hereby superseded and AIP Supplement 05/24 remains current until cancellation notified by a NOTAM.


A. V. M. Sagara Kotakadeniya (Retd.)
Director General of Civil Aviation and
Chief Executive Officer
Civil Aviation Authority of Sri Lanka


Shifted parking stands locations in Apron B and Apron C
















NEW GROUND SERVICE EQUIPMENT ROUTE (GSE)

Appendix B
AIP SUP 05/24
04 APR 2024



Parking Stands Availability & Refueling Schedule

Stands	01 st April 2024 to 31 st December 2024
A1	AVBL/FHS*
A2 to A9	AVBL/FHS*
B10 to B14	AVBL/FHS*
B15	Closed
B16 and B17	AVBL/Manual
B18	Closed
C19 and C26	Closed
C20 to C25	AVBL/Manual
E27 to E35	Closed
E36 to E49	AVBL/FHS*

Remark : E32 to E35 limited for tow operations and idle parking only.

*FHS = Fuel Hydrant System

Note : Please refer the issued NOTAM for updates.